



Improper panel in garage. Cover was not removed due to refrigerator.



The remaining pictures are of the missed nails mentioned on the roof inspection report.





Closet door off the track in rear bedroom.





































Nails that were driven through the drip edge wood.



More nails. There were close to 100 nails like this on this tile roof.



More nails through the drip edge.