


## INSPECTIONS Inc.

### DEFICIENCY PHOTOS



The following three pages of pictures show the numerous missed studs in the attic.



This does not conform to the local building code pertaining to the nailing pattern.



LICENSED  
www.magnuminspections.com  
Phone: (954) 340-6615

# MAGNUM

INSURED  
ev@magnuminspections.com  
Phone: (954) 340-6615

## INSPECTIONS Inc.

### DEFICIENCY PHOTOS





LICENSED

www.magnuminspections.com

Phone: (954) 340-6615

# MAGNUM

INSURED

ev@magnuminspections.com

Phone: (954) 340-6615

## *I N S P E C T I O N S* Inc.

### DEFICIENCY PHOTOS

